IN THE DRAWINGS:

Please amend Fig. 3 in the manner as proposed in the Replacement Sheet showing Fig. 3 to include a signal line 44 issuing a halt to the logic function clock represented at block 37.